

# Oil Field Environmental Incident Summary

**Incident:** 20160620112104      **Date/Time of Notice:** 06/20/2016 11:21

**Responsible Party:** XTO ENERGY INC.

**Well Operator:** XTO ENERGY INC.

**Well Name:** NORMARK 24X-31

**Field Name:** MCGREGOR

**Well File #:** 19484

**Date Incident:** 6/18/2016      **Time Incident:** 0952

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 158

**Rng:** 95

**Sec:** 31

**Qtr:**

**Location Description:**

**Submitted By:** Scot Richardson

**Received By:**

**Contact Person:** Scot Richardson  
P.O Box 6506  
Williston, ND 58802

**General Land Use:** Cultivated

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units
Oil	20	Gallons

Recovered	Units
-----------	-------

Followup	Units
19	gallons

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 6/30/2016

**Clean Up Concluded:** 6/22/2016

**Risk Evaluation:**

none

**Areal Extent:**

70'X6'

**Potential Environmental Impacts:**

Minimal: light oil mist on wellsite surface (scoria) and vegetation.

**Action Taken or Planned:**

Separator was drained and dump was repaired.

**Wastes Disposal Location:** to be determined

**Agencies Involved:**

**Updates**

---

**Date:** 6/20/2016    **Status:** Reviewed - Follow-up Required

**Author:** Schiermeister, Robin

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spill was not contained on site. Further follow-up is needed.

---

**Date:** 6/27/2016    **Status:** Inspection

**Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 1620. Area of release is on a low slant hill near the heater treaters. The area has been mowed and has no visible oil residue. Photos can be found in the report folder. Recommend coming back at a later time to assess vegetation growth.